

Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration
(Non-Mandatory Form)
Form Approved
OMB No. 1218-0072



IDENTITY <i>(As Used on Label and List)</i> MPM DermaPlex Rx Gel	Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that.
---	---

Section I

Manufacturer's Name GDMI, INC.	Emergency Telephone Number 972-840-8980
Address <i>(Number, Street, City, State, and ZIP Code)</i> 2763 Marquis Drive	Telephone Number for Information 972 494-7477
Garland, TX 75042	Date Prepared 8/18/04
	Signature of Preparer <i>(optional)</i>

Section II - Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity; Common Name(s))	OSHA PEL	ACGIH TLV	Other Limits Recommended	% <i>(optional)</i>
None				

Section III - Physical/Chemical Characteristics

Boiling Point	N/A	Specific Gravity (H ₂ O = 1)	1.000
Vapor Pressure (mm Hg)	N/A	Melting Point	N/A
Vapor Density (AIR = 1)	N/A	Evaporation Rate (Butyl Acetate = 1)	N/A
Solubility in Water Soluble			
Appearance and Odor Opaque, white, viscous lotion with a faint characteristic odor.			

Section IV - Fire and Explosion Hazard Data

Flash Point (Method Used) N/A	Flammable Limits N/A	LEL N/A	UEL N/A
Extinguishing Media Water or halon			
Special Fire Fighting Procedures None			
Unusual Fire and Explosion Hazards None			

(Reproduce locally)

OSHA 174, Sept. 1985

Section V - Reactivity Data

Stability	Unstable		Conditions to Avoid
	Stable	X	
Incompatibility (<i>Materials to Avoid</i>) None known			
Hazardous Decomposition or Byproducts None known			
Hazardous Polymerization	May Occur		Conditions to Avoid
	Will Not Occur	X	

Section VI - Health Hazard Data

Route(s) of Entry:	Inhalation? No	Skin? Yes	Ingestion? No
Health Hazards (<i>Acute and Chronic</i>) None			
Carcinogenicity: None	NTP? None	IARC Monographs? None	OSHA Regulated? None
Signs and Symptoms of Exposure None			
Medical Conditions None			
Emergency and First Aid Procedures Flush with water.			

Section VII - Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled
Absorb spill with an inert material and bar, or flush with water to drain.
Waste Disposal Method Dispose in accordance with Federal, Local and State law.
Precautions to Be taken in Handling and Storing None
Other Precautions None

Section VIII - Control Measures

Respiratory Protection (<i>Specify Type</i>) None		
Ventilation	Local Exhaust None	Special None
	Mechanical (<i>General</i>) None	Other None
Protective Gloves Not needed	Eye Protection Not needed	
Other Protective Clothing or Equipment Not needed		
Work/Hygienic Practices Follow good manufacturing practices.		

* U.S.G.P.O.: 1986 - 491 - 529/45775